



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY
SUPERFUND SITE STRATEGY RECOMMENDATION - REGION 06



Site Name: Delta Shipyard

CERCLIS ID#: LAD058475419

Address: Industrial Boulevard

City/County or Parish/State/Zip Code: Houma/Terrebonne/LA

Report Type, Date, and Author: SIP, June 15, 1995, ARCS

RECOMMENDATION

- | | |
|--|---|
| <input type="checkbox"/> 1. No Further Remedial Action Planned (NFRAP) | <input checked="" type="checkbox"/> 2. Further Investigation Needed Under Superfund |
| <input type="checkbox"/> PA | <input type="checkbox"/> HRS |
| <input type="checkbox"/> SI | <input type="checkbox"/> RA |
| <input checked="" type="checkbox"/> ESI | <input type="checkbox"/> RI/FS |
| <input type="checkbox"/> Other: | |
| | To be performed by: ARCS |
| <input type="checkbox"/> 3. Action Deferred to: | |
| <input type="checkbox"/> RCRA | <input type="checkbox"/> NRC |

NOTIFY AUTHORITY:

- | | | | | |
|---|---|--------------------------------|--------------------------------|--|
| <input type="checkbox"/> Removal | <input type="checkbox"/> RCRA | <input type="checkbox"/> TSCA | <input type="checkbox"/> CAA | <input type="checkbox"/> SMCRA |
| <input type="checkbox"/> Remedial | <input type="checkbox"/> State | <input type="checkbox"/> NPDES | <input type="checkbox"/> NRC | <input type="checkbox"/> Resource Trustee: |
| <input type="checkbox"/> CERCLA Enforcement | <input type="checkbox"/> Federal Facility | <input type="checkbox"/> UIC | <input type="checkbox"/> SPCC | <input type="checkbox"/> Other: |
| SEND REPORT COPIES TO: | | <input type="checkbox"/> 6W-SP | <input type="checkbox"/> ATSDR | <input checked="" type="checkbox"/> State Agency |
| <input type="checkbox"/> Other | | | | |

DISCUSSION: The Site Inspection Prioritization (SIP) report for this site prepared by the Alternate Remedial Contracting Strategy (ARCS) contractor was reviewed. This site is an inactive barge cleaning, repairing, and gas-freeing operation. Sources include surface impoundments that were used to hold wastes from site operations. Three of these impoundments are exposed and covered by a black crusty substance. Samples from the impoundments have shown the presence of various organic compounds and metals at levels significantly above background. No ground water use has been identified in the area. The surface water intake for the Houma Water Plant is physically 2.5 miles upstream of the site. However, due to seasonal tidal influence that causes salt water intrusion, there is a potential for site related contaminants to move upstream and affect the quality of water entering the plant. Samples have shown site related compounds in the drainage ditch at the site. There are workers on-site and a nearby population that could be exposed to contamination. Further investigation is necessary at this site, to address the data gaps that were identified in the SIP report. It is recommended that an Expanded Site Inspection be conducted to collect the additional information required to determine if the site will qualify for inclusion on the National Priorities List of Superfund sites.

APPROVALS:

Report Reviewed by: John L. Jones

Signature: John L. Jones

Date: 10/10/95

Disposition Recommended by: Ragan Broyles
(Section Chief)

Signature: Ragan Broyles

Date: 10/10/95

Disposition Approved by: Charles Gazda
(Branch Chief)

Signature: Charles C. Gazda

Date: 10/10/95